

Date :

Gervais Auto Inc Trois-Rivières

2415 Boulevard Thibeau Trois-Rivieres G8T 1G1

1 581 703-8560

Make / Model	
Volkswagen ID.4 Pro Cuir Toit	
Year	Mileage indicated / actual*
2022	75,530 km
Transmission	Drive Type
automatic	RWD
Engine	Fuel Type
	electric
Serial number	Stock number
	BB-*22ID41541



EQUIPMENTS

SALE PRICE

Adaptive cruise control, Air conditioning, Cruise control, Heated mirrors, Power Mirrors, Power driver seat, Power steering, Power windows, Adjustable steering wheel, Heated steering, Driver airbag, Passenger airbag, Rear defrost, Stability control, Traction control, Intermittent wipers, Rain sensor wipers, Two-toned paint, Satellite radio, Bucket seats, Reverse camera, Variable speed intermittent wipers, Child safety locks, Climate control, Integrated turn signal mirrors, Driver vanity mirror, Passenger vanity mirror, Driver illuminated vanity mirror, Pass-Through rear seat, Power passenger seat, Rear head air bag, Front floor mats, Brake assist, Auxiliary audio input, Keyless entry, Auto-on headlights, Keyless start, Audio steering controls

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for:

The dealer will supply upon request the name and phone number of the last owner.

	Category	
Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a: Legal warranty: A - 6 month - 10000 KM	As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warrant for the duration of the term or mileage, whichever is attained first, indicated below: A	
Repairs done and mechanical verification certificate Comments		
The following repairs have been done on this vehicle since the dealer's possession.		
If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.		
Optional repairs		
The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :		

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :



Sticker #:

8588766