

Date:

Gervais Auto Inc Trois-Rivières

2415 Boulevard Thibeau Trois-Rivieres G8T 1G1

1 581 703-8560

Make / Model	
Chevrolet Cruze 1LT Tissus	
Year	Mileage indicated / actual*
2015	76,122 km
Transmission	Drive Type
automatic	FWD
Engine	Fuel Type
4 cyl. / 1.4 liters	unleaded
Serial number	Stock number
	*15CRU8264A



EQUIPMENTS

SALE PRICE

Air conditioning, Cruise control, Heated mirrors, Power Mirrors, Power steering, Power windows, Adjustable steering wheel, Driver airbag, Passenger airbag, Rear defrost, Stability control, Traction control, Intermittent wipers, Two-toned paint, CD player, Satellite radio, Bucket seats, Reverse camera, Variable speed intermittent wipers, Child safety locks, Driver vanity mirror, Passenger vanity mirror, Pass-Through rear seat, Rear head air bag, Front floor mats, Anti-theft system, Front reading lamps, Wheel covers, Auxiliary audio input, Keyless entry, Auto-on headlights, Emergency Trunk Release, Audio steering controls, Export to Shopicar, Export to Shopicar (Company ID): 4068

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for:

The dealer will supply upon request the name and phone number of the last owner.

	Category	
Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a: Legal warranty: D - None (LPC 37,38)	As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below: A 6 months or B 3 months or C 1 month or 1700 km	
	D Good working E No Warranty	
Repairs done and mechanical verification certificate Comments		
The following repairs have been done on this vehicle since the dealer's possession.		
If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.		
Optional repairs		
The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :		

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :



Sticker #:

8417794