

Date :

## Gervais Auto Inc Trois-Rivières

2415 Boulevard Thibeau Trois-Rivieres G8T 1G1

1 581 703-8560

## Make / Model Subaru Crosstrek Touring AWD ... Mileage indicated / actual\* 2018 103.361 km **Transmission Drive Type AWD** manual **Engine Fuel Type** 4 cyl. / 2 liters unleaded Serial number Stock number \*18CRO7280



## **EQUIPMENTS**

**SALE PRICE** 

Air conditioning, Cruise control, Heated mirrors, Power Mirrors, Power steering, Power windows, Adjustable steering wheel, Driver airbag, Passenger airbag, Rear defrost, Stability control, Traction control, Intermittent wipers, Two-toned paint, MP3 Player, Bucket seats, Reverse camera, Variable speed intermittent wipers, Child safety locks, Climate control, Driver vanity mirror, Passenger vanity mirror, Pass-Through rear seat, Rear head air bag, Front floor mats, Anti-theft system, Brake assist, Auxiliary audio input, Keyless entry, Auto-on headlights, Remote trunk release, Audio steering controls

Plus tax.

## Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for:

The dealer will supply upon request the name and phone number of the last owner.

	Category	
Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a:	As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage,	
Legal warranty : C - 1 month - 1700 KM	whichever is attained first, indicated below:	
	A 6 months or B 3 month 5 000 km	hs or C 1 month or 1 700 km
D Good working (subject to 37, 38 L.P.C.) E No warranty		
Repairs done and mechanical verification certificate		Comments
The following repairs have been done on this vehicle since the dealer's possession.		
If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.		
Optional repairs		
The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :		

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :



Sticker #:

8315514