

Date:

Gervais Auto Inc Trois-Rivières

2415 Boulevard Thibeau Trois-Rivieres G8T 1G1

1 581 703-8560

Make / Model Tesla Model 3 GPS Mags Cuir ... Mileage indicated / actual* 2021 59,505 km **Transmission Drive Type** automatic **RWD Engine Fuel Type** electric Serial number Stock number *21TES9272



EQUIPMENTS

SALE PRICE

Air conditioning, Cruise control, Heated mirrors, Power Mirrors, Power driver seat, Power steering, Power windows, Adjustable steering wheel, Driver airbag, Passenger airbag, Rear defrost, Stability control, Traction control, Intermittent wipers, Two-toned paint, Bucket seats, Reverse camera, Variable speed intermittent wipers, Child safety locks, Climate control, Driver vanity mirror, Passenger vanity mirror, Driver illuminated vanity mirror, Mirror memory, Pass-Through rear seat, Power passenger seat, Rear head air bag, Brake assist, Auxiliary audio input, Woodgrain interior trim, Keyless entry, Auto-on headlights, Keyless start, Remote trunk release, Audio steering controls

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for:

The dealer will supply upon request the name and phone number of the last owner.

	Category
Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a: Legal warranty: A - 6 month - 10000 KM	As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below: A 6 months or B 3 months or C 1 month or 1 700 km
	D Good working E No (subject to 37, 38 L.P.C.)
Repairs done and mechanical verification certificate Comments	
The following repairs have been done on this vehicle since the dealer's possession.	
If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.	
Optional repairs	
The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :	

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :



Sticker #:

8519946